


TRUCK	P/N: MA006964	Date	14.11.2008	
MERCEDES BENZ	F/W: C08-T4.1	Start	10:28:38	
Actros (WDB950.0 - 954.3)	N/S: P001670075	Close	10:37:43	

NR, Level regulation

DIAGNOSIS			
1	Height sensor. Operating left axle - Signal interrupted	ERROR PRESENT	0

ECU DATA	
ECU TYPE:	ECAS ENR
REFERENCE NUMBER:	446 170 024 0
DATE:	34/2001

COPY TO MULTIDIAG

DISPLAY CALIBRATION	
NORMAL LEVEL, FRONT:	---
NORMAL LEVEL, REAR RIGHT:	119
NORMAL LEVEL, REAR LEFT:	115
UPPER LEVEL, FRONT:	---
UPPER LEVEL, REAR RIGHT:	190
UPPER LEVEL, REAR LEFT:	186
LOWER LEVEL, FRONT:	---
LOWER LEVEL, REAR RIGHT:	96
LOWER LEVEL, REAR LEFT:	92

CALIBRATE	
THE THREE HEIGHT LEVELS WILL BE CALIBRATED	
LEVEL:	NORMAL
AXLE:	REAR AXLE RIGHT
FRONT:	---
REAR AXLE RIGHT:	119
REAR AXLE LEFT:	255
LEVEL:	UPPER
AXLE:	FRONT
FRONT:	---
REAR AXLE RIGHT:	119
REAR AXLE LEFT:	255
LEVEL:	LOWER
AXLE:	FRONT
FRONT:	---
REAR AXLE RIGHT:	119
REAR AXLE LEFT:	255

SIL, Driver seat regulation

SIN, Central seat regulation

SRS, Retention system

TCO, Tachograph

ECU DATA

REFERENCE NUMBER: *

DATE: */*

DIAGNOSIS IDENTIFICATION: *

ECU DATA

REFERENCE NUMBER: *

DATE: */*

DIAGNOSIS IDENTIFICATION: *

WS, Maintenance system

ECU DATA

REFERENCE NUMBER: 0004460724

DATE: 33/01

DIAGNOSIS IDENTIFICATION: 5

DIAGNOSIS

1	signal CAN - Rear axle 1 left. Wearing pads sensor	ERROR NOT PRESENT	--
2	Water of condensation sensor - Open Circuit	ERROR PRESENT	--
3	CAN line with injection electronics (MR) - Waiting time exceeded (timeout)	ERROR NOT PRESENT	--